

# Detailed Inventory

PWS Name: Aspens Pines Water and Sewer District

PWSID: WY5600220

Date Last Updated: 4/8/23

**Purpose of this worksheet:** To provide a customizable format water systems can use to track materials for each service line in their distribution system.

**General Instructions:** Each row in this worksheet represents one service line connecting the water main to the customer's plumbing. The worksheet includes required and recommended elements; the columns with the aqua shading are required by the LCRR. Systems can customize by adding or deleting columns. Important notes for each column are in Row 12; also see the

Location Information			System-Owned Portion			Customer-Owned Portion					Entire Service Line Material Classification	Other Potential Sources of Lead			Additional Information	
Unique Service Line ID	Location Identifier  Street Address	Sensitive Population? (Yes/No)	System-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Notes		Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Does the Interior Building Plumbing Contain Copper Pipes with Lead Solder Installed Before Your State's Lead Ban (Generally
A Unique ID is recommended for each service line.	Water systems must track addresses of all service lines in their internal inventory. For the publicly accessible version, location identifiers are required for lead and galvanized requiring replacement. If the system does not use addresses for their location identifier, other options could include GPS coordinates, landmark, intersection, block, or other details to specify service line locations.	Select Yes if sensitive subpopulation, e.g., day care, school, multifamily home. If Yes-Other, describe in the Notes field.	Dropdown list includes recommended subclassifications. If "Non-Lead Other", describe in Notes field	Date, year, or estimated date range when the service line was installed or replaced	Diameter in inches	Dropdown list includes recommended subclassifications. If non-lead other, describe in Notes field.	Date, year, or estimated date range when the service line was installed or replaced	Diameter in inches	Select option from dropdown list. If "Other," describe in the Notes field	Can use this field for documenting additional relevant information, including when classification changes.	Dropdown list includes four required service line classifications of Lead, Non-lead, Galvanized Requiring Replacement, or Unknown	For example, lead gooseneck or pigtail where the water main is connected to the service line	Select Yes, No, or Don't Know	For example, backflow preventer or meter containing lead	Note: This information may be helpful for identifying lead tap monitoring locations.	
Athletic Club	4030 N Lake Creek Dr., Wilson, WY 83014	No	Non-Lead - Plastic	10/8/2021	2	Galvanized		2.5	Service line repair or replacement record	2 saddles left on main	Non-Lead	No	No	Building	Unknown	
Bontecou Construction	4020 N. Lake Creek Dr.	No	Non-Lead - Plastic	10/8/2021	2	Galvanized		2.5	Service line repair or replacement record		Non-Lead	No	No	Building	Unknown	
Woodward/Bath Industries	4010 N Lake Creek Dr.	No	Non-Lead - Plastic	9/28/1993	4	Non-Lead - Plastic	1993	4	Service line diameter is > 2 inches		Non-Lead	No	No	Building	Unknown	
Stiegler's	4040 N Lake Creek Dr.	No	Non-Lead - Plastic	10/8/2021	2	Galvanized		2.5	Service line repair or replacement record		Non-Lead	No	No	Building	Unknown	
Sotheby's/BC safaris	4050 N. Lake Creek Drive	No	Non-Lead - Plastic	10/8/2021	2	Galvanized		2.5	Service line repair or replacement record		Non-Lead	No	No	Building	Unknown	
Yoga Shala	3510 N. Lake Creek Drive	No	Non-Lead - Plastic	10/11/2023	1.5	Non-Lead - Plastic	11/17/2023	1.5	Service line repair or replacement record	new from main into building	Non-Lead	No	No	Building	Unknown	
Aspens Market	4015 N Lake Creek Drive	No	Non-Lead - Plastic	11/8/2012	1.5	Galvanized		1	Service line repair or replacement record		Non-Lead	No	No	Building	Unknown	
100 Building	3855 Lake Creek Dr	Yes - Multifamily Home	Galvanized		2	Non-Lead - Plastic	2014	1.5	Service line repair or replacement record	old saddle with 2" galvanized to 1.5" poly to building edge	Non-Lead	Yes	No	Multiple Family Residence	Unknown	
200 Building	3865 Lake Creek Dr	Yes - Multifamily Home	Galvanized		1.5	Non-Lead - Plastic	2007	1.5	Service line repair or replacement record	old saddle w 1.5" galvy to 1.5" IPS poly to 1.5" CTS poly to building edge	Non-Lead	Yes	No	Multiple Family Residence	Unknown	
300 Building	3875 Lake Creek Dr	Yes - Multifamily Home	Non-Lead - Plastic	11/20/2008	1.5	Non-Lead - Plastic	2012	1.5	Service line repair or replacement record	1.5" CTS poly from main into condos. Old saddle abandoned	Non-Lead	No	No	Multiple Family Residence	Unknown	

Location Information			System-Owned Portion			Customer-Owned Portion					Entire Service Line Material Classification	Other Potential Sources of Lead			Additional Information	
Unique Service Line ID	Location Identifier Street Address	Sensitive Population? (Yes/No)	System-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Notes		Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Does the Interior Building Plumbing Contain Copper Pipes with Lead Solder Installed Before Your State's Lead Ban (Generally
400 Building	3635 Lake Creek Dr.	Yes - Multifamily Home	Galvanized		2	Non-Lead - Plastic		1.5	Service line repair or replacement record	2" galvy from main to curb. 1.5" cts poly to 1.5" galvy at building edge	Non-Lead	Yes	No		Multiple Family Residence	Unknown
500 Building	3655 Lake Creek Dr.	Yes - Multifamily Home	Galvanized		2	Non-Lead - Plastic		1.5	Service line repair or replacement record	2" galvy from main to curb. 1.5" cts poly to 1.5" galvy at building edge	Non-Lead	Yes	No		Multiple Family Residence	Unknown
600 Building	3665 Lake Creek Dr.	Yes - Multifamily Home	Non-Lead - Plastic	10/30/2010	2	Non-Lead - Plastic	10/30/2010	1.5	Service line repair or replacement record	new 2" saddle w 2" IPS to 2" cts to 1.5" cts into condo	Non-Lead	No	No		Multiple Family Residence	Unknown
700 Building	3675 Lake Creek Dr.	Yes - Multifamily Home	Non-Lead - Plastic	10/30/2010	2	Non-Lead - Plastic	10/30/2010	2	Service line repair or replacement record	new 2" saddle to 2" poly to 1' poly at building edge	Non-Lead	No	No		Multiple Family Residence	Unknown
800 Building	3685 Lake Creek Dr.	Yes - Multifamily Home	Non-Lead - Plastic	10/30/2010	2	Non-Lead - Plastic	10/30/2010	2	Service line repair or replacement record	new 2" saddle to 2" poly into building	Non-Lead	No	No		Multiple Family Residence	Unknown
900 Building	3705 Teton Dr.	Yes - Multifamily Home	Non-Lead - Plastic	10/15/2018	1.5	Non-Lead - Plastic	10/15/2018	1.5	Service line repair or replacement record	new saddle to 1.5" cts poly to existing 1.5" galvanized at condo edge	Non-Lead	No	No		Multiple Family Residence	Unknown
1000 Building	3885 Lake Creek Dr.	Yes - Multifamily Home	Non-Lead - Plastic	10/24/2018	1.5	Non-Lead - Plastic		1.25	Service line repair or replacement record	new 1.5" saddle w/ 1.5" cts poly to curb and 1.25" cts poly to 1.5" galvy near building edge	Non-Lead	No	No		Multiple Family Residence	Unknown

Location Information			System-Owned Portion			Customer-Owned Portion					Entire Service Line Material Classification	Other Potential Sources of Lead			Additional Information	
Unique Service Line ID	Location Identifier  Street Address	Sensitive Population? (Yes/No)	System-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Notes		Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Does the Interior Building Plumbing Contain Copper Pipes with Lead Solder Installed Before Your State's Lead Ban (Generally
1100 Building	2890 Lake Creek Dr.	Yes - Multifamily Home	Non-Lead - Plastic	4/10/2020	1.5	Non-Lead - Plastic		1.5	Service line repair or replacement record	new 1.5" saddle w/ 1.5" cts poly to 1.5" galvy at condo edge	Non-Lead	No	No		Multiple Family Residence	Unknown
1200 Building	3900 Lake Creek Dr.	Yes - Multifamily Home	Non-Lead - Plastic	4/10/2020	1.5	Non-Lead - Plastic	3/12/2003	1.5	Service line repair or replacement record	new 1.5" saddle w/ 1.5" cts poly to existing 1.5" cts poly into building	Non-Lead	No	No		Multiple Family Residence	Unknown
1300 Building	3910 Lake Creek Dr.	Yes - Multifamily Home	Non-Lead - Copper	12/3/1993	1	Galvanized		1.5	Service line repair or replacement record	1" type K copper from corp to curb. 1.5" galvy curb into building	Non-Lead	Yes	No		Multiple Family Residence	Unknown
1400 Building	3920 Lake Creek Dr.	Yes - Multifamily Home	Non-Lead - Plastic	11/17/2011	1.5	Non-Lead - Plastic	11/17/2011	1.5	Service line repair or replacement record	1.5" CTS poly from main to condo. Old saddle still on main	Non-Lead	No	No		Multiple Family Residence	Unknown
1500 Building	3930 Lake Creek Dr.	Yes - Multifamily Home	Non-Lead - Plastic	11/17/2011	2	Galvanized		1.5	Service line repair or replacement record	2" cts poly main to curb, original 1.5" galvy curb to condo, abandoned saddle	Non-Lead	No	No		Multiple Family Residence	Unknown
1600 Building	3620 Teton Dr.	Yes - Multifamily Home	Non-Lead - Plastic	11/4/2009	1.5	Non-Lead - Plastic	11/4/2009	1.5	Service line repair or replacement record	original saddle to 1.5" cts poly to curb to 1.5" ips poly to condo	Non-Lead	No	No		Multiple Family Residence	Unknown
1700 Building	3630 Teton Drive	Yes - Multifamily Home	Non-Lead - Copper	12/6/1994	1.5	Galvanized		1.5	Service line repair or replacement record	new saddle, 1.5" type K copper to curb, 1.5" galvanized into condo. 2 old saddles abandoned upstream	Non-Lead	No	No		Multiple Family Residence	Unknown
1800 Building	3530 N Lake Creek Dr.	Yes - Multifamily Home	Non-Lead - Copper	11/9/2001	2	Non-Lead - Plastic	4/10/2005	1.5	Service line repair or replacement record	new saddle, 2" type k copper to curb, 2" cts poly to 2nd 1.5" curb, 1.5" IPS poly to condo	Non-Lead	No	No		Multiple Family Residence	Unknown
1900 Building	3545 N Lake Creek Dr.	Yes - Multifamily Home	Non-Lead - Plastic	11/17/2009	2	Non-Lead - Plastic	11/17/2009	1.5	Service line repair or replacement record	new tap, 2" cts poly to curb, 1.5" cts poly into condo	Non-Lead	No	No		Multiple Family Residence	Unknown
2000 Building	3540 N Lake Creek Dr.	Yes - Multifamily Home	Non-Lead - Copper	11/9/2001	2	Non-Lead - Plastic	4/10/2005	1.5	Service line repair or replacement record	new saddle, 2" type k copper to curb, 2" cts poly to 2nd 1.5" curb, 1.5" IPS poly to condo	Non-Lead	No	No		Multiple Family Residence	Unknown
2100 Building	3544 N. Lake Creek Dr.	Yes - Multifamily Home	Non-Lead - Plastic	12/18/2013	1.5	Galvanized	original	1.5	Service line repair or replacement record	new saddle, 1.5" poly to curb, original 1.5" galvanized to condo. 2 old saddles abandoned	Non-Lead	No	No		Multiple Family Residence	unknown
2200 Building	3548 N Lake Creek Dr.	Yes - Multifamily Home	Non-Lead - Plastic	9/14/2012	1.5	Non-Lead - Plastic	9/14/2012	1.5	Service line repair or replacement record	new saddle to 1.5" cts poly into condo. Old saddle abandoned	Non-Lead	No	No		Multiple Family Residence	Unknown
2300 Building	3555 Lake Creek Dr.	Yes - Multifamily Home	Non-Lead - Plastic	11/18/2016	1.5	Non-Lead - Plastic	11/30/2018	1.5	Service line repair or replacement record	new saddle to 1.5" cts poly into condo.	Non-Lead	No	No		Multiple Family Residence	Unknown
2400 Building	3565 N Lake Creek Dr.	Yes - Multifamily Home	Non-Lead - Plastic	11/18/2016	1.5	Non-Lead - Plastic	11/30/2018	1.5	Service line repair or replacement record	new saddle to 1.5" cts poly into condo	Non-Lead	No	No		Multiple Family Residence	Unknown

Location Information			System-Owned Portion			Customer-Owned Portion					Entire Service Line Material Classification	Other Potential Sources of Lead			Additional Information	
Unique Service Line ID	Location Identifier Street Address	Sensitive Population? (Yes/No)	System-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Notes		Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Does the Interior Building Plumbing Contain Copper Pipes with Lead Solder Installed Before Your State's Lead Ban (Generally
2500 Building	3730 N Lake Creek Dr.	Yes - Multifamily Home	Non-Lead - Plastic	11/8/2003	2	Non-Lead - Plastic	11/8/2003	1.5	Service line repair or replacement record	new 2" corp to 2" cts poly to 1.5" cts poly into condo. Old saddle in ground?	Non-Lead	No	No		Multiple Family Residence	Unknown
2600 Building	3720 N Lake Creek Dr.	Yes - Multifamily Home	Non-Lead - Plastic	11/8/2003	2	Non-Lead - Plastic	11/8/2003	1.5	Service line repair or replacement record	new 2" corp to 2" cts poly to 1.5" cts poly to curb, 1.25" cts poly to 1.5" ips poly into building. Old saddle in ground?	Non-Lead	No	No		Multiple Family Residence	Unknown
2700 Building	3715 Teton Dr	Yes - Multifamily Home	Non-Lead - Plastic	10/15/2018	1.5	Non-Lead - Plastic	10/15/2018	1.5	Service line repair or replacement record	new saddle to 1.5" cts poly to existing 1.5" galvanized at condo edge	Non-Lead	No	Yes		Multiple Family Residence	Unknown
2800 Building	3660 Teton Dr.	Yes - Multifamily Home	Non-Lead - Plastic	11/29/2007	2	Non-Lead - Plastic	11/29/2007	1.5	Service line repair or replacement record	new 2" saddle to 2" cts poly to 1.5" cts poly, to 1.5" galvanized at condo edge. Old saddle abandoned	Non-Lead	No	No		Multiple Family Residence	Unknown
2900 Building	3650 Teton Dr.	Yes - Multifamily Home	Non-Lead - Plastic	11/29/2007	2	Non-Lead - Plastic	11/29/2007	1.5	Service line repair or replacement record	new 2" saddle to 2" cts poly to 1.5" cts poly, to 1.5" galvanized at condo edge. Old saddle abandoned	Non-Lead	No	No		Multiple Family Residence	Unknown
3000 Building	4495 Berry Dr.	Yes - Multifamily Home	Non-Lead - Plastic	10/19/2021	1.5	Non-Lead - Plastic	12/21/2021	1.5	Service line repair or replacement record	new saddle with 1.5" cts poly up to the condo edge	Non-Lead	No	No		Multiple Family Residence	Unknown
3100 Building	4485 Berry Dr.	Yes - Multifamily Home	Non-Lead - Plastic	9/13/2017	1.5	Non-Lead - Plastic	9/13/2017	1.5	Service line repair or replacement record	original saddle with new corp. stop and 1.5" cts poly to galvanized at condo edge	Non-Lead	No	No		Multiple Family Residence	Unknown
3200 Building	4475 Berry Dr.	Yes - Multifamily Home	Non-Lead - Plastic	11/5/2020	2	Galvanized	11/5/2020	1.5&2	Service line repair or replacement record	new saddle to 2" cts poly, transition to original 1.5" galvanized 25' from building edge	Non-Lead	No	No		Multiple Family Residence	Unknown
3300 Building	4465 Berry Dr.	Yes - Multifamily Home	Non-Lead - Plastic	11/5/2020	2	Galvanized	11/5/2020	1.5&2	Service line repair or replacement record	new saddle to 2" cts poly, transition to original 1.5" galvanized 25' from building edge	Non-Lead	No	No		Multiple Family Residence	Unknown
3400 Building	4455 Berry Dr.	Yes - Multifamily Home	Galvanized	11/10/2017	1.5	Galvanized		1.5	Service line repair or replacement record	1.5" cts poly from main to 3400 curb, assumed galvy between 3400&3500 curbs. Old saddle abandoned	Non-Lead	No	No		Multiple Family Residence	Unknown

Location Information			System-Owned Portion			Customer-Owned Portion					Entire Service Line Material Classification	Other Potential Sources of Lead			Additional Information	
Unique Service Line ID	Location Identifier  Street Address	Sensitive Population? (Yes/No)	System-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Notes		Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Does the Interior Building Plumbing Contain Copper Pipes with Lead Solder Installed Before Your State's Lead Ban (Generally
3500 Building	4445 Berry Dr.	Yes - Multifamily Home	Galvanized	11/10/2017	1.5	Galvanized	12/17/2002	1.5	Service line repair or replacement record	poly to 3400 curb, assumed 25' original galvy to new curb 8' from condo edge to 1.5" copper into building	Non-Lead	No	No	Multiple Family Residence	Unknown	
3600 Building	4435 Berry Dr.	Yes - Multifamily Home	Non-Lead - Plastic	4/12/2013	1.5	Galvanized		1.5	Service line repair or replacement record	original saddle with new corp. stop and 1.5" cts poly to curb, 1.5" poly to galvy at bldg edge	Non-Lead	No	No	Multiple Family Residence	Unknown	
3700 Building	4425 Berry Dr.	Yes - Multifamily Home	Non-Lead - Plastic	10/21/2018	2	Non-Lead - Plastic	10/21/2018	2	Service line repair or replacement record	new saddle with 2" cts poly to 2" galvanized at condo edge	Non-Lead	No	No	Multiple Family Residence	Unknown	
3800 Building	4420 Berry Dr.	Yes - Multifamily Home	Galvanized		1.5	Galvanized		1.5	Service line repair or replacement record	original	Non-Lead	Yes	No	Multiple Family Residence	Unknown	
3900 Building	4450 Berry Dr.	Yes - Multifamily Home	Non-Lead - Plastic	4/16/2008	2	Non-Lead - Plastic	4/16/2008	2	Service line repair or replacement record	new saddle and 2" cts poly into building	Non-Lead	No	No	Multiple Family Residence	Unknown	
4000 Building	4490 Berry Dr.	Yes - Multifamily Home	Non-Lead - Plastic		2	Non-Lead - Plastic		2	Service line repair or replacement record	2017 new tap, 2" cts poly from main for 20' transition to 2" IPS poly into building. Old tap was left with a new saddle and plug.	Non-Lead	No	No	Multiple Family Residence	Unknown	
4100 Building	3910 Pond Dr.	Yes - Multifamily Home	Non-Lead - Copper	8/5/1988	1.5	Non-Lead - Copper	8/5/1988	1.5	Installation record (e.g., tap card)	original plumbing 1988	Non-Lead	No	No	Multiple Family Residence	No	
4200 Building	3920 Pond Dr.	Yes - Multifamily Home	Galvanized	10/4/1989	1.5	Non-Lead - Copper	10/4/1989	2	Installation record (e.g., tap card)	original plumbing 1989	Non-Lead	No	No	Multiple Family Residence	No	
4300 Building	3950 Pond Dr.	Yes - Multifamily Home	Galvanized	10/4/1989	1.5	Galvanized	10/4/1989	1.5	Installation record (e.g., tap card)	original plumbing 1989	Non-Lead	No	No	Multiple Family Residence	Unknown	
4400 Building	3960 Pond Dr.	Yes - Multifamily Home	Non-Lead - Plastic	10/15/2019	1.5	Non-Lead - Plastic	10/15/2019	1.5	Service line repair or replacement record	New from main into condo in 2019	Non-Lead	No	No	Multiple Family Residence	Unknown	
4500 Building	3970 Pond Dr.	Yes - Multifamily Home	Non-Lead - Plastic	10/15/2019	1.5	Non-Lead - Plastic	10/15/2019	1.5	Service line repair or replacement record	New from main into condo in 2019	Non-Lead	No	No	Multiple Family Residence	Unknown	
4600 Building	3980 Pond Dr.	Yes - Multifamily Home	Non-Lead - Plastic	10/15/2019	1.5	Non-Lead - Plastic	10/15/2019	1.5	Service line repair or replacement record	New from main into condo in 2019	Non-Lead	No	No	Multiple Family Residence	Unknown	
4700 Building	3930 Pond Dr.	Yes - Multifamily Home	Non-Lead - Plastic	10/15/2019	1.5	Non-Lead - Plastic	10/15/2019	1.5	Service line repair or replacement record	New from main into condo in 2019	Non-Lead	No	No	Multiple Family Residence	Unknown	
4800 Building	3940 Pond Dr.	Yes - Multifamily Home	Non-Lead - Plastic	10/15/2019	1.5	Non-Lead - Plastic	10/15/2019	1.5	Service line repair or replacement record	New from main into condo in 2019	Non-Lead	No	No	Multiple Family Residence	Unknown	
5000 Building	3640 Teton Dr.	Yes - Multifamily Home	Non-Lead - Plastic	11/29/2007	1.5&2	Galvanized		1.5	Service line repair or replacement record	New line from main to curb in 2007. Old saddle left on with curb, box at grade.	Non-Lead	No	No	Multiple Family Residence	Unknown	
5100 Building	3425 Teton Dr.	Yes - Multifamily Home	Non-Lead - Plastic	10/19/2018	1.5	Galvanized		2	Service line repair or replacement record	New line from main to building edge in 2018.	Non-Lead	No	No	Multiple Family Residence	Unknown	
5200 Building	3934 S Lake Creek Dr.	Yes - Multifamily Home	Non-Lead - Copper	11/22/1993	1	Non-Lead - Copper	11/22/1993	1	Installation record (e.g., tap card)	original line	Non-Lead	No	No	Multiple Family Residence	No	
5300 Building	3916 S Lake Creek Dr.	Yes - Multifamily Home	Non-Lead - Copper	11/18/1993	1	Non-Lead - Copper	11/18/1993	1	Installation record (e.g., tap card)	original line	Non-Lead	No	No	Multiple Family Residence	No	

Location Information			System-Owned Portion			Customer-Owned Portion					Entire Service Line Material Classification	Other Potential Sources of Lead			Additional Information	
Unique Service Line ID	Location Identifier  Street Address	Sensitive Population? (Yes/No)	System-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Notes		Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Does the Interior Building Plumbing Contain Copper Pipes with Lead Solder Installed Before Your State's Lead Ban (Generally
5400 Building	3883 S Lake Creek Dr.	Yes - Multifamily Home	Non-Lead - Copper	11/22/1993	1	Non-Lead - Copper	11/22/1993	1	Installation record (e.g., tap card)	original line	Non-Lead	No	No		Multiple Family Residence	No
Balsam Lodges	3944&3946 S Lake Creek Dr.	Yes - Multifamily Home	Non-Lead - Plastic	10/8/2021	2	Galvanized		2.5	Service line repair or replacement record	original line from curb to building	Non-Lead	No	No		Multiple Family Residence	Unknown
Aspen Building	3525 N Lake Creek Dr.	Yes - Multifamily Home	Non-Lead - Plastic	10/17/2023	1.5	Non-Lead - Plastic	2018/2019	1	Service line repair or replacement record		Non-Lead	No	No		Multiple Family Residence	Unknown
Wind River Building	3505 Lake Creek Dr.	Yes - Multifamily Home	Non-Lead - Plastic	10/12/2023	1	Galvanized		1	Service line repair or replacement record	new saddle to 1" CTS poly to 3 ft. of 1" copper (2002 repair) to curb to assumed galvanized	Non-Lead	No	No		Multiple Family Residence	Unknown
Spruces Building	3940 S Lake Creek Dr.	Yes - Multifamily Home	Non-Lead - Copper		1.5	Galvanized			Service line repair or replacement record	original line was replaced when interconnect was installed in the late 1980's	Non-Lead	No	No		Multiple Family Residence	Unknown
Woodlands Buildings	3925, 3935 & 3945 S Lake Creek Dr.	Yes - Multifamily Home	Non-Lead - Plastic	10/11/2023	2	Non-Lead - Plastic	2018	2	Service line repair or replacement record		Non-Lead	No	No		Multiple Family Residence	Unknown
Lot 1	3560 Lake Creek Dr.	No	Non-Lead - Plastic	10/19/2023	1	Non-Lead - Copper		1	Service line repair or replacement record		Non-Lead	No	No		Single Family Residence	Unknown
Lot 2	3570 Lake Creek Dr.	No	Non-Lead - Plastic	10/24/2023	1	Non-Lead - Copper		1	Service line repair or replacement record		Non-Lead	No	No		Single Family Residence	Unknown
Lot 3	3580 Lake Creek Dr.	No	Non-Lead - Plastic	10/26/2023	1	Non-Lead - Plastic	3/30/1993	1	Service line repair or replacement record		Non-Lead	No	No		Single Family Residence	Unknown
Lot 4	3590 Lake Creek Dr.	No	Non-Lead - Plastic	11/7/2019	1	Non-Lead - Plastic		1	Service line repair or replacement record	new saddle and 1" cts poly to curb, 1" IPS poly into house	Non-Lead	No	No		Single Family Residence	Unknown
Lot 5	3600 Lake Creek Dr.	No	Non-Lead - Plastic	11/3/2023	1	Non-Lead - Plastic	6/3/1999	1	Service line repair or replacement record		Non-Lead	No	No		Single Family Residence	Unknown
Lot 6	3610 Lake Creek Dr.	No	Non-Lead - Plastic	4/20/2006	1	Unknown - Unlikely Lead			Service line repair or replacement record	new from main into house in 2006. old saddle abandoned	Non-Lead	No	No		Single Family Residence	Unknown
Lot 7	3620 Lake Creek Dr.	No	Non-Lead - Plastic	11/7/2023	1.5	Non-Lead - Plastic		1.5	Service line repair or replacement record		Non-Lead	No	No		Single Family Residence	Unknown
Lot 8	3630 Lake Creek Dr.	No	Non-Lead - Plastic	10/8/2018	1	Non-Lead - Plastic	10/15/2018	1	Service line repair or replacement record	new from main into house in 2018	Non-Lead	No	No		Single Family Residence	Unknown
Lot 9	3636 Lake Creek Dr.	No	Non-Lead - Plastic	11/13/2019	1	Non-Lead - Plastic		1	Service line repair or replacement record	new 1" cts poly from main to curb, existing 1" IPS poly from curb into house	Non-Lead	No	No		Single Family Residence	Unknown
Lot 10	3640 Lakee Creek Dr	No	Non-Lead - Plastic	11/8/2023	1					vacant lot	Non-Lead	No	No		Single Family Residence	
lot 11	3650 Lake Creek Dr	No	Non-Lead - Plastic	11/13/2023	1	Non-Lead - Plastic	2020	1	Service line repair or replacement record		Non-Lead	No	No		Single Family Residence	Unknown
Lot 12	3660 Lake Creek Dr	No	Non-Lead - Plastic	11/15/2023	1	Galvanized		1	Service line repair or replacement record		Non-Lead	No	No		Single Family Residence	Unknown
Lot 14	3670 Lake Creek Dr	No	Unknown - Unlikely Lead	4/4/2000	1	Galvanized		1	Service line repair or replacement record	corp to curb replaced w/ poly old saddle and corp left on main old corp to off position	Non-Lead	No	No		Single Family Residence	Unknown

Location Information			System-Owned Portion			Customer-Owned Portion					Entire Service Line Material Classification	Other Potential Sources of Lead			Additional Information	
Unique Service Line ID	Location Identifier Street Address	Sensitive Population? (Yes/No)	System-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Notes		Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Does the Interior Building Plumbing Contain Copper Pipes with Lead Solder Installed Before Your State's Lead Ban (Generally
Lot 15	3680 Lake Creek Dr	No	Non-Lead - Plastic	11/21/2023	1	Galvanized		3/4			Non-Lead	No	No		Single Family Residence	Unknown
Lot 16	3690 Lake Creek Dr	No	Non-Lead - Plastic	10/30/2018	1	Galvanized		3/4	Service line repair or replacement record	corp to curb replaced w/ 1" poly reuse original saddle hole on main	Non-Lead	No	No		Single Family Residence	Unknown
Lot 17	3700 Lake Creek Dr	No	Non-Lead - Plastic	11/30/2023	1	Non-Lead - Plastic	2004	1	Service line repair or replacement record		Non-Lead	No	No		Single Family Residence	Unknown
Lot 19	3715 Lake Creek Dr	No	Galvanized		1	Galvanized		1	Predictive model	original line	Non-Lead	Yes	No		Single Family Residence	Unknown
Lot 20	3705 Lake Creek Dr	No	Non-Lead - Plastic	4/6/2004	1	Galvanized		1	Service line repair or replacement record	old saddle plugged and abandoned	Non-Lead	No	No		Single Family Residence	Unknown
Lot 21	3695 Lake Creek Dr	No	Non-Lead - Plastic	11/28/2023	1	Galvanized		3/4	Service line repair or replacement record	3/4" galvy near curb, 3/4" IPS poly in crawlspace	Non-Lead	No	No		Single Family Residence	Unknown
Lot 22	3675 Lake Creek Dr.	No	Non-Lead - Plastic	4/8/2021	1	Galvanized		1	Service line repair or replacement record	corp to curb replaced w/1" poly cts	Non-Lead	No	No		Single Family Residence	Unknown
Lot 23	3665 Lake Creek Dr.	No	Non-Lead - Plastic	8/1/2002	1	Non-Lead - Plastic	8/1/2002	1	Service line repair or replacement record	old saddle abandoned with corp off	Non-Lead	No	No		Single Family Residence	Unknown
Lot 24	3655 Lake Creek Dr.	No	Non-Lead - Plastic	11/13/2023	1	Galvanized		3/4	Service line repair or replacement record		Non-Lead	No	No		Single Family Residence	Unknown
Lot 25	3645 Lake Creek Dr	No	Non-Lead - Plastic	11/9/2023	1					vacant lot	Non-Lead	No				
Lot 26	3625 Lake Creek Dr	No	Non-Lead - Plastic	6/29/2004	1	Galvanized		1	Service line repair or replacement record	old saddle abandoned with corp off	Non-Lead	No	No		Single Family Residence	Unknown
Lot 27	3605 Lake Creek Dr	No	Non-Lead - Plastic	11/2/2023	1	Non-Lead - Plastic		1	Service line repair or replacement record		Non-Lead	No	No		Single Family Residence	Unknown
Lot 28	3585 Lake Creek Dr	No	Non-Lead - Plastic	10/29/2022	1	Non-Lead - Plastic	2015-2017	1	Service line repair or replacement record	corp to curb replaced w 1" cts customer service line 1" poly ips	Non-Lead	No	No		Single Family Residence	Unknown
Lot 29	3775 Fish Creek Dr	No	Galvanized		1	Galvanized		1	Previous Materials Evaluation	original service line	Non-Lead	Yes	No		Single Family Residence	Unknown
Lot 30	3755 Fish Creek Dr	No	Non-Lead - Plastic	11/8/2023	1	Non-Lead - Plastic	2005	1	Service line repair or replacement record		Non-Lead	No	No		Single Family Residence	Unknown
Lot 31	3735 Fish Creek Dr	No	Non-Lead - Plastic	9/7/2012	1	Non-Lead - Plastic	9/7/2012	1	Service line repair or replacement record	old saddle abandoned with corp off	Non-Lead	No			Single Family Residence	Unknown
Lot 32	3750 Fish Creek Dr	No	Non-Lead - Plastic	10/15/2021	1	Galvanized		1.5	Service line repair or replacement record	1" poly cts from corp to curb old corp and saddle removed old tap hole used	Non-Lead	No	No		Single Family Residence	Unknown
Lot 33	3575 Lake Creek Dr	No	Non-Lead - Plastic	10/21/2023	1	Non-Lead - Plastic	3/30/2007	3/4	Service line repair or replacement record	3/4 poly from curb to inside house	Non-Lead	No	No		Single Family Residence	Unknown
Lot 76	3880 Lake Creek Dr	No	Non-Lead - Plastic	10/15/2020	1.5	Non-Lead - Plastic	10/15/2020	1.5	Service line repair or replacement record	cts poly from new corp to inside bldg old hole was used w/existing tapping sleeve	Non-Lead	No	No		Other	Unknown
Lot 78	3860 Lake Creek Dr	No	Galvanized		1	Non-Lead - Plastic	12/15/1988	1	Service line repair or replacement record	curb to inside house 1" poly	Non-Lead	Yes	No		Single Family Residence	Unknown
Lot 79	3850 Lake Creek Dr	No	Non-Lead - Plastic	10/1/2021	1	Galvanized		1	Service line repair or replacement record	1"cts poly used corp to curb old hole used	Non-Lead	No	No		Single Family Residence	Unknown

Location Information			System-Owned Portion			Customer-Owned Portion					Entire Service Line Material Classification	Other Potential Sources of Lead			Additional Information	
Unique Service Line ID	Location Identifier Street Address	Sensitive Population? (Yes/No)	System-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Notes		Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Does the Interior Building Plumbing Contain Copper Pipes with Lead Solder Installed Before Your State's Lead Ban (Generally
Lot 80	3840 Lake Creek Dr	No	Non-Lead - Copper	4/28/1994	1	Galvanized		1	Service line repair or replacement record	corp to curb is type K copper existing hole and saddle used pictures	Non-Lead	No	No		Single Family Residence	Unknown
Lot 81	3845 Lake Creek Dr	No	Non-Lead - Plastic	11/30/2005	1	Galvanized		1	Service line repair or replacement record	new corp and saddle new hole 1" poly to existing curb	Non-Lead	No	No		Single Family Residence	Unknown
Lot 82	3849 Lake Creek Dr.	No	Non-Lead - Plastic	11/20/2003	3/4	Non-Lead - Copper	4/10/2002	3/4	Service line repair or replacement record	new from main up to house, likely galvanized at building edge. Old saddle abandoned	Non-Lead	No	No		Single Family Residence	Unknown
Lot 83	3575 Fish Creek Dr.	No	Non-Lead - Plastic	10/18/2019	1	Galvanized		1	Service line repair or replacement record	new from main to curb, 1" cts poly	Non-Lead	No	No		Single Family Residence	Unknown
Lot 84	3605 Fish Creek Dr.	No	Galvanized			Galvanized			Field inspection only with no records	original	Non-Lead	Yes	No		Single Family Residence	Unknown
Lot 85	3625 Fish Creek Dr.	No	Galvanized			Galvanized			Field inspection only with no records	original	Non-Lead	Yes	No		Single Family Residence	Unknown
Lot 86	3635 Fish Creek Dr.	No	Non-Lead - Plastic	9/28/2018	1	Non-Lead - Plastic	4/21/1994	3/4	Service line repair or replacement record	new 1" cts poly from main to curb, existing poly from curb into house	Non-Lead	No	No		Single Family Residence	Unknown
Lot 87	3655 Fish Creek Dr.	No	Non-Lead - Plastic	10/25/2019	1	Non-Lead - Plastic	3/25/1992	3/4	Service line repair or replacement record	new 1" cts poly from main to past curb stop, tied into existing 3/4" IPS poly	Non-Lead	No	No		Single Family Residence	Unknown
Lot 88	3665 Fish Creek Dr.	No	Galvanized			Galvanized			Field inspection only with no records	original	Non-Lead	Yes	No		Single Family Residence	Unknown
Lot 89	3675 Fish Creek Dr.	No	Non-Lead - Plastic	9/28/2018	1	Non-Lead - Plastic	10/14/2018	1	Service line repair or replacement record	new 1" cts poly from main into house	Non-Lead	No	No		Single Family Residence	Unknown
Lot 90	3705 Fish Creek Dr.	No	Non-Lead - Plastic	12/13/2007	1	Galvanized		3/4	Service line repair or replacement record	1" poly from main to curb, 3/4" galvanized on homeowners side in 2007. old saddle abandoned	Non-Lead	No	No		Single Family Residence	Unknown
Lot 91	3725 Fish Creek Dr.	No	Non-Lead - Plastic	11/18/2018	1	Non-Lead - Plastic		3/4 or 1	Service line repair or replacement record	new 1" cts poly from main to curb, existing poly on homeowners side	Non-Lead	No	No		Single Family Residence	Unknown
Lot 92/18	3710 Lake Creek Dr.	No	Non-Lead - Copper	3/23/2000	1	Non-Lead - Plastic	7/6/2000	1	Installation record (e.g., tap card)	1" copper from main to curb, 1" poly from curb into house	Non-Lead	No	No		Single Family Residence	Unknown
Lot 93	3730 Lake Creek Dr.	No	Non-Lead - Copper	4/21/2000	1	Non-Lead - Plastic	4/28/2000	1	Installation record (e.g., tap card)	1" copper from main to curb, 1" poly from curb into house	Non-Lead	No	No		Single Family Residence	Unknown
Lot 94	3740 Lake Creek Dr.	No	Non-Lead - Plastic	10/25/2017	1	Non-Lead - Plastic	10/4/2017	1	Service line repair or replacement record	1" cts poly corp to curb, 1" ips poly from curb into house	Non-Lead	No	No		Single Family Residence	Unknown
Lot 95	3745 Lake Creek Dr.	No	Non-Lead - Plastic	10/26/2022	1	Non-Lead - Plastic	10/26/2022	1	Service line repair or replacement record	1" cts poly from main into house	Non-Lead	No	No		Single Family Residence	Unknown



Location Information			System-Owned Portion			Customer-Owned Portion					Entire Service Line Material Classification	Other Potential Sources of Lead			Additional Information	
Unique Service Line ID	Location Identifier Street Address	Sensitive Population? (Yes/No)	System-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Notes		Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Does the Interior Building Plumbing Contain Copper Pipes with Lead Solder Installed Before Your State's Lead Ban (Generally
Lot 96	3755 Lake Creek Dr.	No	Non-Lead - Plastic	6/15/2020	1	Non-Lead - Plastic	4/11/2000	1	Service line repair or replacement record	original from main to curb, 1" poly from curb into house	Non-Lead	No	No	Single Family Residence	Unknown	
Lot 97	3750 Lake Creek Dr.	No	Non-Lead - Plastic	11/3/2021	1	Non-Lead - Plastic	11/3/2021	3/4&1	Service line repair or replacement record	new from main up to building edge, short section of 1.25" galvanized remains going into house	Non-Lead	No	No	Single Family Residence	Unknown	
Lot 98	3760 Lake Creek Dr.	No	Galvanized			Non-Lead - Plastic	10/22/1997	1	Installation record (e.g., tap card)	original to curb, 1" poly from curb into house	Non-Lead	Yes	No	Single Family Residence	Unknown	
Lot 99	3775 Lake Creek Dr.	No	Galvanized			Galvanized			Previous Materials Evaluation	original	Non-Lead	Yes	No	Single Family Residence	Unknown	
Lot 100	3785 Lake Creek Dr.	No	Galvanized			Galvanized			Previous Materials Evaluation	original	Non-Lead	Yes	No	Single Family Residence	Unknown	
Lot 101	3795 Lake Creek Dr.	No	Galvanized			Non-Lead - Plastic	4/21/2016	1	Installation record (e.g., tap card)	original on our side	Non-Lead	Yes	No	Single Family Residence	Unknown	
Lot 102	3805 Lake Creek Dr.	No	Non-Lead - Copper	12/5/2002	3/4	Galvanized		3/4	Service line repair or replacement record	our side replaced 2002, old saddle abandoned	Non-Lead	No	No	Single Family Residence	Unknown	
Lot 103	3815 Lake Creek Dr.	No	Galvanized			Galvanized			Previous Materials Evaluation	original	Non-Lead	Yes	No	Single Family Residence	Unknown	
Lot 104	3835 Lake Creek Dr.	No	Non-Lead - Plastic	3/31/2020	1	Galvanized		3/4	Service line repair or replacement record	1" cts poly from main to curb, original 3/4" galvanized on owners side	Non-Lead	No	No	Single Family Residence	Unknown	
Lot 105	3825 Lake Creek Dr.	No	Galvanized			Galvanized			Previous Materials Evaluation	original	Non-Lead	Yes	No	Single Family Residence	Unknown	
Lot 106	3810 Lake Creek Dr.	No	Non-Lead - Plastic	11/24/2022	1	Non-Lead - Plastic	10/1/2021	1	Service line repair or replacement record	new from main to house	Non-Lead	No	No	Single Family Residence	Unknown	
Lot 107	3800 Lake Creek Dr.	No	Galvanized			Galvanized			Service line repair or replacement record	original	Non-Lead	Yes	No	Single Family Residence	Unknown	
Lot 108	3790 Lake Creek Dr.	No	Non-Lead - Plastic	11/10/2006	3/4	Non-Lead - Copper	4/20/1994	1	Installation record (e.g., tap card)	3/4" cts poly from main to curb, 1" copper from main to house old saddle abandoned	Non-Lead	No	No	Single Family Residence	Unknown	
Lot 109	3780 Lake Creek Dr.	No	Non-Lead - Copper	10/23/1990	3/4	Galvanized		3/4	Service line repair or replacement record	3/4" copper from main to curb, original 3/4" galvanized curb to house. Old saddle abandoned	Non-Lead	No	No	Single Family Residence	Unknown	
Lot 110	3770 Lake Creek Dr.	No	Galvanized			Galvanized			Previous Materials Evaluation	original	Non-Lead	Yes	No	Single Family Residence	Unknown	
Lot 112-vacant	4405 Lake Creek Dr.															
Lot 113-vacant	4455 Cottonwood Dr.															
Lot 114	4855 Cottonwood Dr.	No	Non-Lead - Plastic	4/8/2016	1	Non-Lead - Plastic	4/5/2016	1	Service line repair or replacement record	1" cts poly on our side, 1" ips poly on owners side. Old saddle abandoned	Non-Lead	No	No	Single Family Residence	Unknown	

Location Information			System-Owned Portion			Customer-Owned Portion					Entire Service Line Material Classification	Other Potential Sources of Lead			Additional Information	
Unique Service Line ID	Location Identifier Street Address	Sensitive Population? (Yes/No)	System-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Notes		Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Does the Interior Building Plumbing Contain Copper Pipes with Lead Solder Installed Before Your State's Lead Ban (Generally
Lot 115	4480 Cottonwood Dr.	No	Non-Lead - Plastic	10/2/1986	1	Galvanized			Service line repair or replacement record	1" poly on our side, assuming original galvanized on owners side. Old saddle abandoned	Non-Lead	No	No		Single Family Residence	Unknown
Lot 116	4450 Cottonwood Dr.	No	Non-Lead - Plastic	11/15/2023	1	Non-Lead - Plastic	10/20/2003	1	Service line repair or replacement record	1" CTS poly to 1" ips poly on owners side	Non-Lead	No	No		Single Family Residence	Unknown
Lot 117	4400 Cottonwood Dr.	No	Non-Lead - Plastic	4/5/2012	3/4	Non-Lead - Plastic	4/5/2012	3/4	Service line repair or replacement record	new line in 2012 from main into house. Old line abandoned and pressurized from corp to curb.	Non-Lead	No	No		Single Family Residence	Unknown
Lot 118	3830 Willow Dr.	No	Non-Lead - Copper	11/7/1988	1	Non-Lead - Plastic		1.5	Service line repair or replacement record	1" copper from main to curb, 1.5" or 2" poly from curb to house.	Non-Lead	No	No		Single Family Residence	Unknown
Lot 119	4425 Willow Dr.	No	Non-Lead - Copper	11/7/1988	1	Galvanized		3/4	Service line repair or replacement record	1" copper from main to curb, 3/4" galvanized on owners side.	Non-Lead	No	No		Single Family Residence	Unknown
Lot 120	4455 Willow Dr.	No	Non-Lead - Copper	11/8/1988	1	Galvanized		1	Service line repair or replacement record	There is a buried curb stop near here that is pressurized up to curb. See notes	Non-Lead	No	No		Single Family Residence	Unknown
Lot 121	4475 Willow Dr.	No	Non-Lead - Copper	11/8/1988	1	Galvanized			Service line repair or replacement record	5' section of poly to repair copper on our side.	Non-Lead	No	No		Single Family Residence	Unknown
Lot 122-vacant	4470 Willow Dr.															
Lot 123	4450 Willow Dr.	No	Non-Lead - Copper			Non-Lead - Copper	6/9/1993	1	Installation record (e.g., tap card)	original on our side	Non-Lead	No	No		Single Family Residence	Unknown
Lot 124	4420 Willow Dr.	No	Non-Lead - Copper			Non-Lead - Copper	5/29/1996	1	Installation record (e.g., tap card)	original on our side	Non-Lead	No	No		Single Family Residence	Unknown
Lot 125	4400 Willow Dr.	No	Non-Lead - Plastic	10/10/2023		Non-Lead - Plastic	5/12/1998	1	Installation record (e.g., tap card)	1" CTS poly to 1" ips poly on owners side	Non-Lead	No	No		Single Family Residence	Unknown
Lot 56	3915 Lake Creek Dr.	No	Non-Lead - Plastic	11/1/2023	1	Non-Lead - Plastic	11/1/2023	1	Installation record (e.g., tap card)	new construction	Non-Lead	No	No		Single Family Residence	Unknown
Yoga Shala 2	3510 N. Lake Creek Drive	No	Non-Lead - Plastic	10/15/2023	1.5				Service line repair or replacement record	vacant lot	Non-Lead	No	No		Building	Unknown